


DETAIL 5: Typical 2.5" ADA Assembly



| Thickness | CRITICAL FALL HEIGHT | | REVISIONS | | | |
|------------------------|--------------------------|------|----------------|------------|----------|--|
| | | REV | DESCRIPTION | DATE | APPROVAL | |
| | | 0 | Original Issue | 06/03/2010 | Ron Loyd | |
| | | | | | | |
| 2.50" | 6.0' | | | | | |
| | | | | | | |
| | | | | | | |
| File Name EMC100.40 | Prepared By: J. Steel | | | | | |
| SHEET SO | | CALE | DWG No. | FSCM | FSCM No. | |
| | | | | | | |